

This PDF is generated from: <https://www.2xt.com.pl/04-02-23-7550.html>

Title: BCM lost communication with base station

Generated on: 2026-05-01 11:05:01

Copyright (C) 2026 2XT Power. All rights reserved.

For the latest updates and more information, visit our website: <https://www.2xt.com.pl>

---

Fix the U0141 network code. Master BCM diagnostics, check power, test CAN bus resistance, and determine necessary module replacement.

Test the BCM and PCM for faults using a diagnostic scanner and replace if necessary. Check and replace any blown fuses or relays related to the communication system. Perform a software update ...

Diagnostic Trouble Code (DTC) U0140 indicates a faulty Body Control Module (BCM) or bad wiring within your vehicle.

The loss of communication errors are not unusual when you have something plugged in to the OBD port. The signal connection is shared by all the computers in the car, it doesn't have a lot ...

To bring this to a close it looks like it is the BCM. I went to my old shop connected a diagnostic tool and interrogated all the modules. The BCM was failing on several fronts... The ECM ...

The U0140 code stands for "Lost Communication With Body Control Module (BCM)", which usually means the BCM isn't properly transmitting or receiving signals from various switches ...

A U0140 code, which indicates a "lost communication with the Body Control Module (BCM)," typically costs between \$300 and \$600 to fix. The primary expense is the replacement of the BCM itself, along ...

In simple terms, the body control module monitors functions and systems on the application that do not involve management of the engine, fuel system, or the operation of the brakes ...

If you've seen the U0140 error code pop up, it signifies a lost communication with your vehicle's Body Control Module (BCM). This can indicate a breakdown in communication between the BCM and ...



## BCM lost communication with base station

Used a friends more expensive scanner and got multiple short to ground codes for the BCM. Ordered a used BCM off eBay. Should be here in the next few days, will post updated when I ...

Web: <https://www.2xt.com.pl>

